ALLOYWELD INSPECTION COMPANY, INC.
BENSENVILLE, IL 60106
796 MAPLE LANE

10/17/2012

SALE

Total: $400.00

Master Card	xxxxxxxxxxxx3990
Exp. Date:	xx / xx
Name:	FERMILAB

Auth. Code:	081339	QuickBooks Trans. No:	
Trans. ID:	MC0094703360	Merchant No.:	5247710003524295

X _____

Signature

I agree to pay the total amount shown above in compliance with the cardholder agreement

MERCHANT COPY

Invoice

ALLOYWELD INSPECTION CO., INC.
796 MAPLE LANE
BENSENVILLE, IL 60106
PH. (630) 595-2145 FAX. (630) 595-2128
www.alloyweldinspection.com

DATE	INVOICE #
10/17/2012	22932

BILL TO:

FERMILAB
ACCOUNTS PAYABLE
P.O. BOX 500
BATAVIA, IL 60510

Please remit to:
Alloyweld Inspection Co., Inc.
796 Maple Lane
Bensenville, IL 60106

P.O. NUMBER	TERMS	PROJECT
PRN163271	Net 30	

QUANTITY	DESCRIPTION	RATE	AMOUNT
1	MD-433897 WELD	250.00	250.00
1	MD-433897 DIGITAL RADIOGRAPHY	150.00	150.00

You can now pay your bill using VISA and MasterCard! If you would like to pay this invoice with a Credit Card, please call 630-595-2145.

TOTAL USD $400.00

© 2003 INTUIT INC. # 515 1-800-433-8810

ALLOYWELD INSPECTION CO. INC.
796 MAPLE LANE
BENSENVILLE, IL 60106
PHONE: 630-595-2145 FAX: 630-595-2128

PACKING SLIP

Date	Number
10/17/2012	22932

Name / Address
FERMILAB ACCOUNTS PAYABLE P.O. BOX 500 BATAVIA, IL 60510

Purchase Order
PRN163271

Quantity	Description
	MD-433897 WELD MD-433897 DIGITAL RADIOGRAPHY INSPECTION REPORT ATTACHED
	Alloyweld Work Order Number -

RECEIVED BY:_____

INSPECTION REPORT ATTACHED [ ] YES [ ] NO
** Please initial if report is received**
Additional Charge for Report Copies or Changes

ALLOYWELD INSPECTION COMPANY, INC.

796 MAPLE LANE PHONE: (630) 595-2145 FAX: (630) 595-2128 BENSENVILLE, ILLINOIS 60106-1585

X-RAY INSPECTION REPORT

READER SHEET

TO:

FERMILAB
KIRK RD & WILSON ST.
BATAVIA, IL 60510

DATE: OCTOBER 9, 2012
ORDER NO: PRN163271
REGISTER NO: 22932
WORK ORDER NO:
PAGE 1 OF 1

INSPECTION INFORMATION

PART NUMBER	MD-433897	MATERIAL	ALUM	HEAT CODE	
FILM NUMBER	X808	NO OF VIEWS	1	NO OF FILM	(2)CR SHOTS
PROCESSED IN ACCORDANCE WITH:	NAS 1514, CL. 1				

X-RAY SERIAL NUMBER	Accept	Non-Conforming	Cracks	Shrinkage	Shrink Cavities	Porosity	Gas Holes	Voids	Surface	REMARKS OR OTHER DISCONTINUITIES
SN: 1		X								TUNGSTEN
SN: 2	X									

This report is limited to the defects of the type that can be located with the above method. Any changes to shaded areas make this report vc

ACCEPTABLE 1 PCS.
NON-CONFORMING 1 PCS.

ALLOYWELD INSPECTION - RADIOGRAPHER SIGNATURE

JENNIFER ANAYA
NAS 410 / MIL-STD-410E LEVEL 3

ALLOYWELD INSPECTION COMPANY, INC.

796 MAPLE LANE PHONE: (630) 595-2145 FAX: (630) 595-2128 BENSENVILLE, ILLINOIS 60106-1585

X-RAY INSPECTION REPORT

READER SHEET

TO:

FERMILAB
KIRK RD & WILSON ST.
BATAVIA, IL 60510

DATE: OCTOBER 16, 2012
ORDER NO: PRN163271
REGISTER NO: 22932
WORK ORDER NO:
PAGE 1 OF 1

INSPECTION INFORMATION

PART NUMBER	MD-433897		MATERIAL	ALUM	HEAT CODE
FILM NUMBER	X808	NO OF VIEWS	1	NO OF FILM	(2)CR SHOTS
PROCESSED IN ACCORDANCE WITH:	NAS 1514, CL. 1				

X-RAY SERIAL NUMBER	Accept	Non-Conforming	Cracks	Shrinkage	Shrink Cavities	Porosity	Gas Holes	Voids	Surface	REMARKS OR OTHER DISCONTINUITIES
SN; 1	X									

This report is limited to the defects of the type that can be located with the above method. Any changes to shaded areas make this report vc

ACCEPTABLE 1 PCS.
NON-CONFORMING 0 PCS.

ALLOYWELD INSPECTION - RADIOGRAPHER SIGNATURE

JENNIFER ANAYA
NAS 410 / MIL-STD-410E LEVEL 3